

Release Notes – sceneCOM

Valid for the following Tridonic products:

- 28003778 sceneCOM evo DA2
- 28002680 sceneCOM L (discontinued)
- 28002681 sceneCOM XL (discontinued)
- 28002682 sceneCOM XL EM (discontinued)
- 28002683 sceneCOM XL EM BAC (discontinued)

sceneCOM 2.16.8

30.05.2023

Others:

- Bug fixes and performance improvements

sceneCOM 2.16.6

21.03.2022

Improvements:

- sceneCOM version 2.16.6 has new default timeouts. The default timeout value is now set to 10 minutes for both functions and duration tests.

sceneCOM 2.16.5

21.12.2021

Improvements:

- sceneCOM version 2.16.5 provides a correction for a critical security vulnerability in widely used java library called "log4j"

sceneCOM 2.16.2

28.5.2021

New features:

- Network settings of controllers are now also stored in backup files

Improvements:

- GUI problems with Chrome v90
 - Special luminaires are not available during creation
 - Configuration and addressing issues fixed
 - GUI issues with "double-click" actions on Windows based touchpanels
 - Daylight linked relay modules have been partly not reacting
 - Missing and wrong pictures in Czech language
-

sceneCOM 2.16.1

8.4.2021

New features:

- Support of DALI-2 certified sensors (daylight and presence) – only available on sceneCOM evo DA2 HW!
- Support of DALI-2 certified push-button input couplers – only available on sceneCOM evo DA2 HW!
- User management
- Controller linking via Ethernet
- Software license handling
- Czech language support

Improvements:

- Optimized algorithm for DALI-2 sensors
- New types of BACnet datapoints for optimization of BMS integration

Bug fixes:

- Various improvements on User Interface
 - Improvements on sensor configuration and commissioning
 - Various improvements on system stability
-

sceneCOM 2.14.0

19.10.2020

Bug fixes:

- Icons are missing for specific devices in BACnet
 - "mode of operation" is not working for the whole room
 - Copying scenes for areas doesn't work
 - cond scene recall loses all Entries after copying and changing the effective range
 - After refresh localhost is displayed instead of the IP-address
 - Day/night show not supported for the special cases: day period goes over midnight, polar day, polar night
 - emergency automatic test does not start
 - Visual issues on home screen
 - Conditional scene recall: copied twilight entry doesn't work
 - Scene configuration/settings is only saved after edit/confirm (No change when scene is recalled)
 - Page title - Misleading page title
 - Overlapping timeframes result in an endless waiting screen
 - Wrong alignment of the TRIDONIC logo on the homescreen
 - Update do not refresh web-page
 - Backup Restore is not working, displaying an error pop up during the process
 - Show doesn't start when scene is called by operating device
 - Infinity: Show preview indicates wrong running state information
 - Show doesn't start if scene is triggered by automation service
-

sceneCOM 2.9.2

Bug fixes:

- BACnet: EDE export does not work
 - Show: intensity cannot be disabled in show
 - Show: show cannot be imported
-

sceneCOM 2.8.1

31.7.2019

Improvements:

- Function test: one or more self-contained emergency luminaires report “emergency operation” status during a function test. The test is now completed for the remaining self-contained emergency luminaires.
- Size of firmware file has been reduced.

Bug fixes:

- Show sometimes has wrong values when scene is recalled...
 - Show sometimes does not work...
-

sceneCOM 2.7.0

6.5.2019

Software changes and improvements in this release:

- Fixed possible problems with Emergency testbook export
- Fixed possible fault lock state of Emergency luminaires
- Fixed possible download failure of a configured Show
- Fixed wrong texts and images in the Web interface